



Inspection / Valuation

Inspected By:	JV / JB	Date:	24/8/18	Customer:	
---------------	---------	-------	---------	-----------	--

Rig

	Model	S/N	Valuation Range		Valuation Avg
Container	Javelin	7417	£100.00	£200.00	£150.00
Reserve	Transfair	DL016B	£100.00	£150.00	£125.00
Main	Katana	KA120-001205	£800.00	£1,200.00	£1,000.00
AAD					£0.00
Totals			£1,000.00	£1,550.00	£1,275.00

Reserve Due:	
AAD Service:	

Other Notes:

This inspection was carried out by XDream Ltd on the basis that all information provided by the customer is correct. I hereby certify that the information provided here represents a fair and true evaluation of the equipment at the time of inspection.

Signed:

Jack Bradford
Director

Please Note: This report is subjective to the opinion of the inspector only, any valuation, if provided, is subject to the current market conditions and is based on multiple contributing factors. It is therefore provided as a guideline only.

For further information, please contact info@xdsports.uk



Inspection / Valuation

Reserve

Inspected By:	JV / JB	Date:	24/8/18	Customer:	
Manufacturer:		Model:	Transfair	Size:	128
S/N:	DL016B	DOM:	19/01/1995	Colours:	White
Line Type:		Links:	No 5 Rapide (har	Slider:	
Features:					

Feature	Condition	Notes	Work Suggested
	0 = New, 1 / 2 = Serviceable, 3 / 4 = Unserviceable, X = Not Present		
Fabric	1		
Lines	1		
Slider	1		
Links	1		

Other Notes: No jump / packing history

New Value:		Valuation Estimate:	£100-£200
------------	--	---------------------	-----------

This inspection was carried out by XDream Ltd on the basis that all information provided by the customer is correct. I hereby certify that the information provided here represents a fair and true evaluation of the equipment at the time of inspection.

Signed:

Jack Bradford
Director

Please Note: This report is subjective to the opinion of the inspector only, any valuation, if provided, is subject to the current market conditions and is based on multiple contributing factors. It is therefore provided as a guideline only.

For further information, please contact info@xdsports.uk



Inspection / Valuation

Container

Inspected By:		Date:		Customer:	
JB		19/01/19			
Manufacturer:	Sunpath	Model:	Javelin	Size:	NJ
S/N:	7417	DOM:	March 1995	Colours:	Black
Harness:	C17	Main Lift Web:	17"	Laterals:	
Features:					

Feature	Condition	Notes	Work Suggested
	0 = New, 1 = Good, 2 = Fair, 3 = Poor, 4 = Unserviceable, X = Not Present		
BOC Pocket	2	Not factory original	
Main Tray	2	No bridle cover (old design), stiffeners and grommets all good, small repair to top flap binding, minor wear on pin cover flap	
Reserve Tray	3	Notable sun damage to outside of container	
Reserve Risers	2	Cadmium coating wearing off toggle guide rings	
Main Lift Web	3	Small amount of rust forming on base 3 ring, minor fraying top of chest strap, cadmium coating worn off chest strap buckle	
Legstraps	2	Padding sun faded	
Main Risers	2		
D-Bag	2	Some grommet discolouration. Possibly not factory original	
Bridle	0	New rigger made kill line bridle	
Pilot Chute	1		
Handle	1	Pipe	

Other Notes: Well used but serviceable container

New Value:		Valuation Estimate:	£100 - 200
-------------------	--	----------------------------	------------

This inspection was carried out by XDream Ltd on the basis that all information provided by the customer is correct. I hereby certify that the information provided here represents a fair and true evaluation of the equipment at the time of inspection.

Signed:

Jack Bradford
Director

Please Note: This report is subjective to the opinion of the inspector only, any valuation, if provided, is subject to the current market conditions and is based on multiple contributing factors. It is therefore provided as a guideline only.

For further information, please contact info@xdsports.uk



Inspection / Valuation

Main

Inspected By:	JV / JB	Date:	24/8/18	Customer:	
---------------	---------	-------	---------	-----------	--

Manufacturer:	PD	Model:	Katana	Size:	120
S/N:	KA120-001205	DOM:	05/06	Colours:	RED/BLU/YEL
Line Type:	HMA	Links:	Soft Links	Slider:	Drawstring
Features:					

Feature	Condition	Notes	Work Suggested
	0 = New, 1 = Good, 2 = Fair, 3 = Poor, 4 = Unserviceable, X = Not Present		
Top Skin	1	Patch to Center Cell tail	
Bottom Skin	1		
Centre Cell	1		
Lines	1		
Slider Stops	1		
Brake Lines	1	Vectran	
Slider	2	Modification to centre of slider	
Links	1		

Other Notes: Jump numbers unknown. Estimated < 200

New Value:	£2,350.00	Valuation Estimate:	£800 - £1200
-------------------	-----------	----------------------------	--------------

This inspection was carried out by XDream Ltd on the basis that all information provided by the customer is correct. I hereby certify that the information provided here represents a fair and true evaluation of the equipment at the time of inspection.

Signed:

Jack Bradford
Director

Please Note: This report is subjective to the opinion of the inspector only, any valuation, if provided, is subject to the current market conditions and is based on multiple contributing factors. It is therefore provided as a guideline only.

For further information, please contact info@xdsports.uk